







































Bull & Loader

Lot No. _____

Model	BD2G	Serial No.	2B600692
Year	1989	Hour	1540?

◆ Accessories ◆

Front	Straight • S/T • Angle • <u>6-way</u> • Bucket • Other () • None
Rear	M/S • S/S • Other () • <u>None</u>
Lift Cylinder	<u>OK</u> • NG ()
Tilt Cylinder	<u>OK</u> • NG ()
Angle Cylinder	<u>OK</u> • NG ()
Ripper Cylinder	<u>OK</u> • NG ()
Bucket Cylinder	<u>OK</u> • NG ()

Comment: _____

◆ Engine ◆

Engine Model: S4E2

Exhaust Color	<u>OK</u> • NG ()
Blow-by	<u>OK</u> • NG ()
Radiator	<u>OK</u> • NG ()
Engine Oil	<u>OK</u> • NG ()
Starter	<u>OK</u> • NG ()

Comment: _____

◆ Crack Welding Patch ◆

Comment: _____

*This report is only for your reference.**We are not responsible for actual conditions of checked items on this list.*

Important Notice!!

FOB Charge:

JPY _____

Place: _____

◆ Under Carriage ◆

	Left	Right
Shoe <u>500</u> (mm)	<u>LGP</u>	<u>LGP</u>
Link		
Pin Bush		
Idler (Shaft)	☒ Normal ☐ Need Repair	☒ Normal ☐ Need Repair
Sprocket		
Carrier Roller		
Track Roller (5) pcs.	○ ○ ○ ○ ○	○ ○ ○ ○ ○
Average	Good ☐ ☒ Poor	Good ☐ ☒ Poor

Comment: _____

◆ Operation Component ◆

A/C	Yes • <u>No</u>	Heater • Cooler
Throttle	<u>OK</u> • NG ()	
Steering	<u>OK</u> • NG ()	
Foot Brake	<u>OK</u> • NG ()	
Parking Brake	<u>OK</u> • NG ()	

Transmission	Forward	(<u>3</u>) gear	Reverse	(<u>3</u>) gear
<u>D/D</u> • P/S				

Comment: _____